




To meet the 300fps / 1J power limit using a M100 spring, spring cut is necessary. The steps are shown in our **AirsoftPRESS Supplemental Video: Spring Cut** Youtube video.

Below shows the minimum extent of spring cut that will be necessary:



You will need these: